

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,952,091 B2  
DATED : October 4, 2005  
INVENTOR(S) : Nitin Bansal

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 5.


Line 54, replace "transistor," with -- transistor; --.

Column 7.

Lines 6-7, replace "generate control signal" with -- generate a control signal --.

Signed and Sealed this

Tenth Day of January, 2006



JON W. DUDAS  
*Director of the United States Patent and Trademark Office*